

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program June 28, 2011

2011	
(KYN)	
Reviewed:	

on Date: June 1 2011		
Inspection Date: June 1, 2011		
2:50 – 3:10 pm		
Mine Status:		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

Purpose of Inspection:

This was a routine inspection.

There are two mines in the area with similar names. The east project is located near the Demison Mine.

Inspection Summary:

The Operator is current on the permit fees. The bond amount is \$6,000.00 and due for renewal in November 25, 2011. The Division will send a letter notifying the Operator of the bond renewal.

There are no shafts, adits or highwalls on the site.

The site does have berms to control erosion.

Conclusions and Recommendations:

The Division should continue to monitor the site and request a bond escalation from the Operator.

Inspection Date: June 21, 2011

Page 2 of 3 S/017/0001

Inspector's Signature WHW:

cc: (OPERATOR)

Sue Fivecoat, BLM John Blake, SITLA

 $O: \label{lem:lemoval-line} O: \label{lemoval-line} O: \label{lemoval-line}$

Maple Weeter



Stockpile looking east



Stockpile looking east